

FIGURE 1




FIGURE 2

FIGURE 3




FIGURE 3

FIGURE 4




FIGURE 5  
A schematic diagram of a coin-operated machine.




FIGURE 5




FIGURE G




FIGURE H